

# Oil Field Environmental Incident Summary

**Incident:** 20150306165527      **Date/Time of Notice:** 03/06/2015 16:55

**Responsible Party:** Blackduck Power Equipment, Inc.

**Well Operator:** WHITING OIL AND GAS CORPORATION

**Well Name:** ERICKSON 152-103-26-35-2H

**Field Name:** GLASS BLUFF

**Well File #:** 25032

**Date Incident:** 3/6/2015      **Time Incident:** 03:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 152

**Rng:** 103

**Sec:** 26

**Qtr:**

**Location Description:**

**Submitted By:** Sue Travers

**Received By:**

**Contact Person:** Mike Sparby  
PO Box 357  
Watford City, ND 58854

**General Land Use:** Badlands Terrain

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	8	Barrels	8	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

No risk

**Areal Extent:**

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

Cleaned up

**Wastes Disposal Location:** Back into tank

**Agencies Involved:**

**Updates**

---

**Date:** 3/6/2015      **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill remained on location. NDIC retains oversight.